

- F. (1) GOOD
  - (2) FAIR

9L/8402/225-9-5-4-3

- (3) GOOD
- (4) GOOD
- (5) GOOD
- (6) GOOD OVERLAP FRAME 3249
- (7) CLEAR
- G. TAKE RECEIVED 26/0640 IN STEEL BOX. ALL TAKE REVIEWED. WRINKLES AND TEARS CAUSED BY MALFUNCTION IN HTA-2 SQUEEZEES. WRINKLES IN FRAME NBRS. 005-016R, 028R, 045-46R, 228-231R, 1109-

SECRET

GROUP 1 recently from automatic documentating and

## Approved For Release 2000/08/28 : CIA-RDP66B00664R000300030026-7

CRIMP 5974 (IN 92942)

PAGE TWO

1118R. TEARS IN 365-366L, 935H. STATIC MARKS 805L AND 1055-55R. MACHINE SCRATCHES 1940-43L, 1949-50L. OUT OF FOCUS FRAMES AT MODE CHANGE. MFG. SPLICES 068H, 650L, 5173L. PLUS DENSITY SPOTS 1090R, 1093R, 1104A. ENGLISION DEFECTS 1892, 1105, 1156, 1102, 1167, 1175, 1259, 1263, 1289, 1364, 1340-47, 1354-56, 1378, 1428, 1555, 1559, 1562-63, 5469, 5473-77, 5344-45, 3553, 3565 ALL R STDE 2249L, 2470L. MINUS DENSITY SPOTS 805-815L, 21152R 1175R, 2015-17K, 2078K. ORIGINAL STILL BEING USED TO OCCOMPLISH DUPLICATING REQUIREMENTS.

H. HOS COURTER APPROXIMETLY 29/12/02 .

SHOW OF MESSAGE